



Telcom Splicing Connectors UR-Gel Filled

P/N multiple

The Telcom Splicing Connectors utilize an insulation displacement contact design for fast, simple, reliable terminations. No wire stripping is required and connectors will accept wire of different gauges. All connectors are Gel filled to provide moisture resistance and inhibit corrosion. For use with solid copper conductors only. Typical uses include Butt Splicing 2 or 3 wires of the same or different gauges. Perfect for pigtail and load coil splice applications. Use the UB connector for tapping onto an existing conductor with no service interruption. This eliminates cutting of cable pairs or opening cable pairs.



- 19-26 AWG, 2 or 3 Wire Splice.
- Use for Butt Splicing 2 or 3 wires.
- Wires can be of different wire gauges.
- Max. insulation O.D, .066

Part Numbers

18110

UR-Gel Filled, 19-26 AWG. 100 Piece Box.

18111

UR-Gel Filled, 19-26 AWG. 25 Piece Retail Clamshell.

18112C

UR Gel-Filled Connector, 19-26 AWG. 50/Clamshell.

28110J

UR-Gel Filled, 19-26 AWG. Jar of 200.

Tips

How you use your tools is just as important as what tool you choose for an application.

T568A/T568B Wiring Chart

Great cheat sheet.

F and RG6 Quad

No more stab wounds.

Cut Strip Terminate Test

Copyright © 2018 Platinum Tools®. All rights reserved.